## **OSHA Regulations**

OSHA is very specific about skylights, which under their interpretation is considered a hole within the roof and as such should be guarded by a cover, a guardrail around the screen or a personal fall arrest system.

## **OSHA States:**

\*OSHA 1926.501(b)(4) Each employee on walking/working surfaces shall be protected from falling through holes (**including skylights**) more than 6 feet (1.8 m) above lower levels, by personal fall arrest systems, covers, or guardrail systems erected around such holes.

## For the original text visit:

http://osha.gov/pls/oshaweb/owadisp.show\_document?p\_table=STANDARDS&p\_id=10757